



Pit cleaning Texas, USA

A customer in the Austin Chalk region in Texas has several pits with water flowing from its producing wells. These pits had excess oil and algae and needed treatment. In addition to this, customer was not satisfied as he had been approached by the EPA and had concerns about them shutting down his operation.

Treatment with Micro-Bac International bacterial products for oil fields began. A monthly treatment program of M-1000H™ and Micro-Bac™ products was implemented.

After two months of treatment, crude oil levels in the Micro-Bac treated pits declined dramatically and water cleanliness was evident. Customer was very satisfied and decided to expand Micro-Bac's treatment to the majority of its pits with similar problems.

Before Treatment



After Treatment

